Doffer Drive Idler Gear

Models 9960 – CP690

Version 1.7





RM KING COMPANY

EMAIL: INFO@RMKING.COM
TEL: 559.266.0258

Doffer Drive Idler Gear

Models 9960 – CP690

Version 1.7

ID	Part Number	Description	Model	MFG
1	N33203	Nut	9960-9965	RMK
2	14M7291	Flange Nut - M16		OEM
3	24H1402	Washer	9960-9965	OEM
4	24H1373	Washer - M16	9970-CP690	OEM
5	N197052	Doffer Idler Gear	9960-9965	RMK
6	N273955	Doffer Idler Gear	9970-9996	RMK
7	JD8674	Ball Bearing	9960-9965	RMK
8	AN272787	Ball Bearing	9970-CP690	RMK
9	E63526	Nut - M10	9970-CP690	RMK

ID	Part Number	Description	Model	MFG
10	N195727	Spacer	9960-9965	OEM
11	N278451	Spacer	9970-CP690	OEM
12	03H2339	Bolt - 3/4 x 2-1/2	9960-9965	RMK
13	03M7211	Bolt - M16 x 70	9970-CP690	OEM
14	N275053	Bracket	9970-CP690	OEM
15	19M7784	Bolt - M10 x 20	9970-CP690	RMK
16	Kit-Idler	Kit - Idler	9960-CP690	RMK
17	N273955SR	Snap Ring	9970-CP690	RMK

Notes:

1. N33203 replaces K40016.
5. N197052 is AN193601 gear and JD8674 as an assembly.
16. Kit-Idler replaces factory bolt 03M7211, washer 24H1373, and nut N33203. Requires new square nut to be tack welded to bottom of support bracket N275053. Kit resolves issues of flexing and cracking of cabinet base plate.
17. N273955SR comes with N2739555 RMK replacement for OEM or can be purchased separately.

EMAIL: INFO@RMKING.COM
TEL: 559.266.0258